# WINDSTREAM COMMUNICATIONS ANNUAL REPORT

FOR THE STATE OF

# <u>lowa</u>

State of Respondent 6/26/2012

### **ETC's Included In This Report**

	LEGAL ENTITY NAME	SAC
ETC#1:	Windstream Iowa Communications, Inc.	351167
ETC#2:	Windstream Iowa Communications, Inc.	351170
ETC#3:	Windstream Iowa Communications, Inc.	351178
ETC#4:	Windstream Montezuma, Inc.	351248
ETC#5.		

ETC#5: ETC#6:

Person to contact for questions:

Name:

Jeff Heacox

Phone Number:

501-748-5390

E-mail Address:

jeff.l.heacox@windstream.com



For The Year Ended December 31, 2011

# **TABLE OF CONTENTS**

# Schedule

-	General Information
#1	Five Year Progress Report
#2	Detailed Outage Report
#3	Unfulfilled Request Report
#4	Number of Complaints per 1,000 Report
#5	Service Quality and Emergency Situation Certification
#6	Company Price Offering Report
#7	Holding and Operating Company Report
#8	Tribal Land Information
#9	Areas With No Terrestial Backhaul Certification
#10	Residential Local Service Rates Report
	Annual Penart Certification

### **GENERAL INFORMATION**

- The enclosed reports are being filed with the Office of the Secretary of the Commission, with the Administrator (USAC), the relevant state commissions, and relevant authority in a U.S. Territory, or Tribal governments, as appropriate pursuant to WC Docket No. 10-90.
- 2. The enclosed information satisfies the requirements included in 47CFR 54.314 and is being provided to:

Marlene H. Dortch, Secretary Federal Communications Commission Office of The FCC Secretary 445 12th Street, SW Washington, D.C. 20554

Universal Service Administrative Company 2000 L Street N.W. Suite 200 Washington, DC 20036 hcfilings@usac.org

Tribal Government as appropriate

3. The Windstream officer signing the certifications included in this report is:

Name: John Fletcher Title: General Counsel

### Report 1 - Five-year Progress Report

§ 54.313(a)(1) A progress report on its five-year service quality improvement plan pursuant to 54.202(a), including maps detailing its progress towards meeting its plan targets, an explanation of how much universal service support was received and how it was used to improve service quality, coverage, or capacity, and an explanation regarding any network improvement targets that have not been fulfilled in the prior calendar year. The information shall be submitted at the wire center level or census block as appropriate;

Response: This requirement is not effective until April 1, 2013 per FCC DA 12-147 II.A.7.

- (i) At least ten percent of the end users served in a designated service area; or
- (ii) A 911 special facility, as defined in 47 CFR 4.5(e).
- (iii) Specifically, the eligible telecommunications carrier's annual report must include information detailing:
  - (A) The date and time of onset of the outage;
  - (B) A brief description of the outage and its resolution;
  - (C) The particular services affected;
  - (D) The geographic areas affected by the outage;
  - (E) Steps taken to prevent a similar situation in the future; and
  - (F) The number of customers affected.

Service Area					Service			Customers
(SAC)	<b>Onset Date</b>	Onset Time	Report Description	Found Description	Affected	Outage Area	Prevention	Affected
				40 min tollisolation due to ss7				
			IA_STAN: CAT SET STAN	links down. due to storm in				
351167	22-Mar-11	8:20 PM	CCS7	area	Local	STANIAXO	Replaced faulty hardware	665
			NEVDIAVODEO NEVO ELL	1				
			NEVDIAXCDSO_NEVD_FU. ITSU_4500_FIBER_MAJOR					
			MAJOR ALARM DETECT					
			ED: NEVDIAXCDS0 GTD-5					
351167	30-Mar-11	6:45 PM	(NEVD) FUJITSU 450	2820	Local	NEVDIAXC	Replaced faulty hardware	36,524
331107	30-Iviai-11	0.43 F W	IA FRCY:DMS10:FRCY FIE		Local	NEVDIANC	Replaced facily flatoware	30,324
			ER ALM_MAJ:	,				
			FRCYIAXODSO DMS-10					
			(FRCY) FRCY	Quest repaired a cut fiber.			Connecting company	
351167	23-May-11	1:04 PM	FIBER ALM MAJ	Sites are back ins.	Local	SWCYIAXO	repaired cut cable	530
331107	25-Way-11	1.041141	TIDEN_ALIV_IVIA	Sites are back ins.	Local	344611770	repaired cut cable	330
			IA_STAN:DMS10:CCS154:					
			FLTRouteset Unavailable					
			STANIAXODSO ANSI7 222	far end trouble cleared both			Reviewed procedures	
351167	25-May-11	7:46 AM	060 038	ss7 links restored close ticket.	Local	STANIAXO	with Telco employee	665
			IA_ARMS:ARMSIAXPDSO:					
			SS7 - ALL LINKS IN					
			LINKSET OOS (TOLL	CABLE SPLICED, SERVICE			Repaired or replaced cut	
351167	05-Jul-11	5:26 PM	ISOLATED)	RESTORED 2200 HRS.	Local	ARMSIAXP	cable	760
			IA_EMBG:EMBGIAXPDS0:			,		
			SS7 - ALL LINKS IN					
			LINKSET OOS(TOLL	CABLE SPLICED, SERVICE			Repaired or replaced cut	
351167	05-Jul-11	5:26 PM	ISOLATED)	RESTORED 2200 HRS.	Local	EMBGIAXP	cable	3,560

- (i) At least ten percent of the end users served in a designated service area; or
- (ii) A 911 special facility, as defined in 47 CFR 4.5(e).
- (iii) Specifically, the eligible telecommunications carrier's annual report must include information detailing:
  - (A) The date and time of onset of the outage;
  - (B) A brief description of the outage and its resolution;
  - (C) The particular services affected;
  - (D) The geographic areas affected by the outage;
  - (E) Steps taken to prevent a similar situation in the future; and
  - (F) The number of customers affected.

Service Area					Service			Customers
(SAC)	<b>Onset Date</b>	Onset Time	Report Description	Found Description	Affected	Outage Area	Prevention	Affected
				40 min tollisolation due to ss7				
			IA_STAN: CAT SET STAN	links down. due to storm in				
351167	22-Mar-11	8:20 PM	CCS7	area	Local	STANIAXO	Replaced faulty hardware	665
			IA_HRTL:HRTLIAXPDSO:					
			SS7 - ALL LINKS IN					
			LINKSET OOS(TOLL	CABLE SPLICED, SERVICE			Repaired or replaced cut	
351167	05-Jul-11	5:26 PM	ISOLATED)	RESTORED 2200 HRS.	Local	HRTLIAXP	cable	2,350
			AR_STPA/STPB: 313: DPC					
			is prohibited -> DPC_222-	· Cleared while testing. Site no			Scheduled additional	
351167	11-Jul-11	3:44 PM	060-042	longer isolated.	Local	SLTRIAXO	testing	949

			. –	_				
351167	11-Jul-11	3:44 PM	060-042	longer isolated.	Local	SLTRIAXO	testing	949
				ISSUE RESOLVED, NOW IN				
				QWEST HANDS				
				Event ID: @16151 -				
				EXCHANGE OUTAGE				
				Event Category: DOutage				
				Status: @CLOSED				
				Start Time: @07/16/2011 7:08				
				PM EDT				
				ETR BUNKNOWN				
				FCC Reportable On:				
			Clark County IA 911	207/16/2011 10:27 PM EDT				
			Outage: PSAP totally	Ticket #: 2INC000007808469			Connecting company	
351167	16-Jul-11	6:45 PM	down	Service Impacted:	E911	OSCLIAXD	repaired cut cable	4,503

- (i) At least ten percent of the end users served in a designated service area; or
- (ii) A 911 special facility, as defined in 47 CFR 4.5(e).
- (iii) Specifically, the eligible telecommunications carrier's annual report must include information detailing:
  - (A) The date and time of onset of the outage;
  - (B) A brief description of the outage and its resolution;
  - (C) The particular services affected;
  - (D) The geographic areas affected by the outage;
  - (E) Steps taken to prevent a similar situation in the future; and
  - (F) The number of customers affected.

Service Area					Service			Customers
(SAC)	Onset Date	Onset Time	Report Description	Found Description	Affected	Outage Area	Prevention	Affected
				40 min tollisolation due to ss7				
			IA_STAN: CAT SET STAN	links down. due to storm in				
351167	22-Mar-11	8:20 PM	CCS7	area	Local	STANIAXO	Replaced faulty hardware	665
							Scheduled additional	
351167	02-Sep-11	7:22 AM	IA_STAN: Toll Isolated	Both SS7 links auto restored	Local	STANIAXO	testing	665
			IA_NHTN_IAHZTN:	Spans auto cleared.				
			NHTNIAXCDS0 ALM031:	DNLD/RTS ESAC HZTN LCE 01			Scheduled additional	
351167	20-Nov-11	7:00 PM	MAJ SET NHTN NED	3.	Local	HZTNIAXO	testing	444
			IA NUTNIAUTTI CRIV	Mike restored the pelps that were smb but the srlk nhtn ce 3 4 4 0 will come out of *rts inprog tech will handle srlk this morning per Mike				
		and appropriate distance in	IA_NHTN IAHZTN SRLK (NT4T24) NHTN CE 03 4 04 0 LAST LINK TO REMOTE BEING	> stat lcm hztn lce 1 1  LCMC (NT6X51) HZTN LCE 01 1 INS ENBL NORM				
351167	21-Nov-11	2:22 AM	REMOVED	SRLK (NT4T24)	Local	HZTNIAXO	Replaced faulty hardware	349
			IA_FRCY WLBGIAXODS0: ALM031: MAJ SET WLBG	Larry called in to see if it was still toll isolated was able to call co # and 1 dlnk was back			Scheduled additional	
351167	22-Nov-11	2:44 AM	DLC	in svc	Local	FRCYIAXO	testing	939
351167	03-Dec-11	7:09 PM	IA_RDFD: MSCO003: RECOVER ALP.TCU0.1.5	Tarps installed and 3 power supplies replaced	Local	RDFDIAXO	Replaced faulty hardware	497

- (i) At least ten percent of the end users served in a designated service area; or
- (ii) A 911 special facility, as defined in 47 CFR 4.5(e).
- (iii) Specifically, the eligible telecommunications carrier's annual report must include information detailing:
  - (A) The date and time of onset of the outage;
  - (B) A brief description of the outage and its resolution;
  - (C) The particular services affected;
  - (D) The geographic areas affected by the outage;
  - (E) Steps taken to prevent a similar situation in the future; and
  - (F) The number of customers affected.

Service Area (SAC)	Onset Date	Onset Time	Report Description	Found Description	Service Affected	Outage Area	Prevention	Customers Affected
(SAC)	Oliset Bute	Oliset Time	report bescription	40 min tollisolation due to ss7	Allected	Outage Area	Ficacinton	Allecteu
			IA STAN: CAT SET STAN	links down, due to storm in				
351167	22-Mar-11	8:20 PM	CCS7	area	Local	STANIAXO	Replaced faulty hardware	665
	***		LOGNIAXOO1Y FAC 1-2-1-	REPLACED FAULTY SFP IN				
351167	20-Dec-11	6:20 AM	1 LOS	MNDMIAXOO1Y 1-3-1-1	Special	MNDMIAXO	Replaced faulty hardware	28,896
				Notes IA_STAN 911 Trunks				
				oos				
				LARRY/TECH, CALLED AND				
				SAID THEY FOUND TROUBLE,				
				HAD CABLE PAIR MIXED UP				
				AND THEY REPAIRED THE				
				CABLE PAIRD. PSAP ARE				
				GETTING CALLS, BUT				
				CANNOT GET ADDRESS, OR				
				NUMBERS.				
				PER JEFF DUPICE/MANAGER,			Repaired or replaced cut	
351167	30-Dec-11	10:42 AM	IA_STAN 911 Trunks OOS	WILL LEAVE LIKE IT IS UNTIL	E911	STANIAXO	cable	665
			KNVLIAXCDS0: PM107:	Tech replaced bad OC-48				
351170	10-May-11	11:00 PM	CBSY RCC EDVL 4	card in KNVL	Local	EDVLIAXP	Replaced faulty hardware	2,478
				Detailed Description of what				
			IA_FRFD : E911 :	was done to repair the				
			JEFFERSON CO. IOWA,	Outage: CPE. FUSES BLOWN				

- (i) At least ten percent of the end users served in a designated service area; or
- (ii) A 911 special facility, as defined in 47 CFR 4.5(e).
- (iii) Specifically, the eligible telecommunications carrier's annual report must include information detailing:
  - (A) The date and time of onset of the outage;
  - (B) A brief description of the outage and its resolution;
  - (C) The particular services affected;
  - (D) The geographic areas affected by the outage;
  - (E) Steps taken to prevent a similar situation in the future; and
  - (F) The number of customers affected.

Service Area					Service			Customers
(SAC)	Onset Date	Onset Time	Report Description	Found Description	Affected	Outage Area	Prevention	Affected
				40 min tollisolation due to ss7				
			IA_STAN: CAT SET STAN	links down. due to storm in				
351167	22-Mar-11	8:20 PM	CCS7	area	Local	STANIAXO	Replaced faulty hardware	665
				Talked to Scott with Century				
				Link, he stated they were still				
				working on the fiber, but he				
				· · · · · · · · · · · · · · · · · · ·				
				is happy to hear our stuff is				
				back up. They were still trying				
			IA CNCT 011 to the	to bring up a DS3 (not our's).				
			IA_GNCT 911 trunks out	Called 319-267-2410 and 319-				
2-44-0		=	of the DMS10 switch are	824-6933 and informed them	7 1	CHETHANA	Connecting company	
351170	12-Aug-11	7:38 PM	down	all is back to no	Local	GNCTIAXO	repaired cut cable	4,811
				Tech patched serial links to				
				spare fiber terminal after				
				l existing failed. Returned				
			G ADBN PE 6 4 6 0 LAST	serial links and both				
351170	17-Aug-11	4:37 AM	LINK TO REMOTE	controllers to service.	Local	HLBRIAXO	Replaced faulty hardware	823
			IA DWTT: ALM031: CAT					
			The manager of the property of the property of the party	-				
			SET DWTT DED/ DEFAULT					
254472		=	LCM718: LCMC (NT6X51)	Tech found burnt BIC card in		BURTING	5 1 15 5 1	050
351170	24-Aug-11	7:40 AM	DWTT LCE 03 1	LSG 8/9	Local	DWTTIAXO	Replaced faulty hardware	852
			IA DWTT:IA TPTN:: All	Cut cable has been repaired.			Repaired or replaced cut	
351170	06-Oct-11	10:45 AM	Ckts busy	Verified site to be ins.	Local	DWTTIAXO	cable	10,334

- (i) At least ten percent of the end users served in a designated service area; or
- (ii) A 911 special facility, as defined in 47 CFR 4.5(e).
- (iii) Specifically, the eligible telecommunications carrier's annual report must include information detailing:
  - (A) The date and time of onset of the outage;
  - (B) A brief description of the outage and its resolution;
  - (C) The particular services affected;
  - (D) The geographic areas affected by the outage;
  - (E) Steps taken to prevent a similar situation in the future; and
  - (F) The number of customers affected.

Service Area					Service			Customers
(SAC)	<b>Onset Date</b>	Onset Time	Report Description	Found Description	Affected	<b>Outage Area</b>	Prevention	Affected
				40 min tollisolation due to ss7			-	
			IA_STAN: CAT SET STAN	links down. due to storm in				
351167	22-Mar-11	8:20 PM	CCS7	area	Local	STANIAXO	Replaced faulty hardware	665
			IA_AVOC ISOLATED					
			HRLN:CAT SET HRLN	Cut cable has been repaired.			Repaired or replaced cut	
351170	24-Oct-11	12:34 PM	FIBER_TERMNL_ALM	Site is in service.	Local	AVOCIAXO	cable	1,698
			IA_ADBN: SRI200: SRLK	Spans to the HLBR, AUBN,				
			(NT4T09) ADBN PE 06 4	VAIL, & MNNG remotes				
			18 0 LAST LINK TO	dropped and restored on				
			REMOTE BEING	their own. NTF per Local tech			Scheduled additional	
351170	27-Oct-11	6:07 PM	REMOVED	on WFM comments.	Local	ADBNIAXO	testing	1,431
			IA_MNPL_IADNSN: Fiber	Techs located and respliced			Repaired or replaced cut	
351178	05-Jan-11	12:19 PM	cut causing E-911 outage	fiber	E911	MNPLIAXC	cable	0
				: Qwest called to cancel			Notified connecting	
			IA_NWTN_IAMONR:	dispatch. CPE issue.CLOSE			company of procedural	
351178	08-Feb-11	1:18 PM	ANI/ALI AFFECTED	TICKET	E911	MONRIAXO	problem	986
				looped back at remote and				
			IA_CLIT: CLITIAXODS0	changed 2t41 and 2t42 pshf				
351178	26-May-11	4:51 AM	DMS-10 (CLIT) CLIT REM	cards.	Local	CLITIAXO	Scheduled Outage	355
			IA_RCCY:RCCYIAXCDS0:					
			STOP-PROCESSOR	CABLE SPLICED, SERVICE			Repaired or replaced cut	
351178	05-Jul-11	5:26 PM	PC.RSU4 (530 lines)	RESTORED 2200 HRS.	Local	FONDIAXO	cable	537

- (i) At least ten percent of the end users served in a designated service area; or
- (ii) A 911 special facility, as defined in 47 CFR 4.5(e).
- (iii) Specifically, the eligible telecommunications carrier's annual report must include information detailing:
  - (A) The date and time of onset of the outage;
  - (B) A brief description of the outage and its resolution;
  - (C) The particular services affected;
  - (D) The geographic areas affected by the outage;
  - (E) Steps taken to prevent a similar situation in the future; and
  - (F) The number of customers affected.

Service Area			***		Service			Customers
(SAC)	Onset Date	Onset Time	Report Description	Found Description	Affected	Outage Area	Prevention	Affected
	,	_		40 min tollisolation due to ss7				
			IA_STAN: CAT SET STAN	links down. due to storm in				
351167	22-Mar-11	8:20 PM	CCS7	area	Local	STANIAXO	Replaced faulty hardware	665
			KNVLIAXC02W: 313: 222-	No links showing down from				
			060-028 DPC is prohibited	the KNVLIA or NWTNIA STPs				
			-> DPC_222-060-028	at this time. Jim W advised				
			NWTNIAXC01W: REPT-	his KNVLIA EXT fiber system			Repaired or replaced cut	
351178	05-Jul-11	5:26 PM	LKF: lost data	alarm also cleared.	Local	KNVLIAXC	cable	16,767
	0.00		IA_CLIT_IACNSV MAJ	Fiber cut has been repaired	*	(1		
			SET CLIT REM/DED/SEE	and spans to the CNSV			Repaired or replaced cut	
351178	28-Sep-11	1:08 PM	NOTE5	remote is back in service.	Local	CNSVIAXO	cable	203
			POSSIBLE FIBER CUT					
			BETWEEN LONE TREE	ALL FIBER SPLICING				
351178	06-Oct-11	11:10 AM	AND NICHOLS IA	COMPLETE	Special	MNPLIAXC	Scheduled Outage	11,424

§ 54.313(a)(2) Detailed information on any outage in the prior calendar year, as that term is defined in 47 CFR 4.5, of at least 30 minutes in duration for each service area in which an eligible telecommunications carrier is designated for any facilities it owns, operates, leases, or otherwise utilizes that potentially affect

- (i) At least ten percent of the end users served in a designated service area; or
- (ii) A 911 special facility, as defined in 47 CFR 4.5(e).
- (iii) Specifically, the eligible telecommunications carrier's annual report must include information detailing:
  - (A) The date and time of onset of the outage;
  - (B) A brief description of the outage and its resolution;
  - (C) The particular services affected;
  - (D) The geographic areas affected by the outage;
  - (E) Steps taken to prevent a similar situation in the future; and
  - (F) The number of customers affected.

Service Area					Service			Customers
(SAC)	<b>Onset Date</b>	<b>Onset Time</b>	Report Description	Found Description	Affected	Outage Area	Prevention	Affected
				40 min tollisolation due to ss7				
			IA_STAN: CAT SET STAN	links down. due to storm in				
351167	22-Mar-11	8:20 PM	CCS7	area	Local	STANIAXO	Replaced faulty hardware	665
				> stat rem cljt pe 8 6 12				
				TIME MON 04:45:00				
				14/11/11				
				04:45:00				
				OCM (NT2T34) CLIT PE 08				
				6 12 SMB DSBL NORM				
				RCM (NT2T32) LTTS PE 03				

6 11 SMB

| IA\_CLIT\_IALTTS | MAJ SET | > busy ? | LTTS REM / MAJ SET CLIT | PSHF DCM | DTRK REM | REM / RCM (NT2T32) LTTS | PSC2 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC2 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | LRNG LCMC | REM / RCM (NT2T32) LTTS | PSC3 LSGD LSG | RNG LCMC | REM / RCM (NT2T32) LTTS | RCM / RCM (NT2T32) LTTS | RCM / RCM (NT2T32) LTTS | RCM / RCM / RCM (NT2T32) LTTS | RCM / R

AM PE 03 6 11 OVLY = DED SC Local LTTSIAXO Replaced faulty hardware

355

DSBL NORM

# Report 3 – Unfulfilled Request Report

§ 54.313(a)(3) The number of requests for service from potential customers within the recipient's service areas that were unfulfilled during the prior calendar year. The carrier shall also detail how it attempted to provide service to those potential customers;

Service Area (SAC)	Wire Center	Held Orders	Held Due To
351167	ELMAIAXO	1	Cable full, added new plant
351167	HRPRIAXO	1	Cable full, added new plant
351167	HZTNIAXO	1	Cable full, added new plant
351167	LOGNIAXO	1	Cable full, added new plant
351167	<b>SGRNIAXP</b>	2	Cable full, added new plant
351167	STANIAXO	1	Cable full, added new plant
351167	WLBGIAXO	1	Cable full, added new plant
351170	APTNIAXO	1	Cable full, added new plant
351170	<b>GNFDIAXO</b>	1	Cable full, added new plant
351178	KNVLIAXC	1	Cable full, added new plant
351178	MLCHIAXO	2	Cable full, added new plant
351178	PELLIAXO	1	Cable full, added new plant

SAC	Wire Center	Complaints/1K		
351167	ALTVIAXP	1		
351167	ARMSIAXP	2		
351167	ARTNIAXO	2		
351167	BLENIAXO	2		
351167	BLLPIAXO	2		
351167	BRVLIAXO	3		
351167	CETNIAXC	2		
351167	CHLSIAXO	2		
351167	CLBGIAXP	1		
351167	CLNSIAXO	3		
351167	CLRDIAXT	1		
351167	CLSPIAXO	2		
351167	<b>CMBRIAXO</b>	3		
351167	CNCYIAXO	1		
351167	CNRYIAXO	1		
351167	CRESIAXO	1		
351167	CYLNIAXO	1		
351167	DELHIAXO	2		
351167	DELTIAXO	3		
351167	DESTIAXP	2		
351167	DLVRIAXO	3		
351167	DNLPIAXO	2		
351167	DXTRIAXO	1		
351167	DYVLIAXO	1		
351167	<b>EDWDIAXO</b>	1		
351167	<b>EKHTIAXP</b>	2		
351167	<b>ELMAIAXO</b>	2		
351167	<b>EMBGIAXP</b>	1		
351167	<b>EPWOIAXO</b>	2		
351167	<b>ERVLIAXP</b>	1		
351167	<b>FRBNIAXO</b>	1		
351167	<b>FRCYIAXO</b>	1		
351167	FRLYIAXO	1		
351167	<b>GDJTIAXO</b>	2		
351167	<b>GLBKIAXP</b>	2		
351167	GLDNIAXO	2		

Page 14

SAC	Wire Center	Complaints/1K		
351167	GRELIAXO	2		
351167	GRNLIAXC	1		
351167	GRWNIAXO	3		
351167	HLCRIAXP	1		
351167	HPTNIAXO	1		
351167	HRPRIAXO	4		
351167	HRRSIAXP	1		
351167	HRTLIAXP	1		
351167	HZTNIAXO	1		
351167	KENTIAXO	2		
351167	KEOTIAXP	2		
351167	LAMTIAXO	1		
351167	LDYRIAXO	2		
351167	LGRDIAXO	2		
351167	LHVLIAXP	2		
351167	LKCYIAXO	2		
351167	LNDNIAXO	2		
351167	LOGNIAXO	3		
351167	LTSXIAXO	3		
351167	LXBGIAXO	1		
351167	MCBGIAXO	1		
351167	<b>MGNLIAXP</b>	3		
351167	MLCMIAXO	2		
351167	MLRDIAXO	1		
351167	MLVNIAXP	2		
351167	MNCHIAXO	1		
351167	MNDMIAXO	2		
351167	MNSNIAXP	2		
351167	MNTRIAXO	2		
351167	MODLIAXO	3		
351167	MRNGIAXO	1		
351167	<b>MXWLIAXP</b>	3		
351167	MYCYIAXP	2		
351167	<b>NEVDIAXC</b>	1		
351167	<b>NWVNIAXP</b>	2		
351167	OCHYIAXP	2		

Page 15

SAC	Wire Center	Complaints/1K		
351167	ORNTIAXP	2		
351167	OSCLIAXD	1		
351167	OXFRIAXP	2		
351167	PANMIAXO	1		
351167	PERSIAXP	3		
351167	<b>PMRYIAXO</b>	2		
351167	PRCVIAXO	3		
351167	PRMGIAXP	2		
351167	PRSCIAXO	2		
351167	PRTVIAXO	2		
351167	<b>PSGHIAXO</b>	4		
351167	PTMOIAXP	3		
351167	<b>RCCYIAXC</b>	1		
351167	<b>RDFDIAXO</b>	1		
351167	RLTNIAXO	2		
351167	RNBCIAXO	1		
351167	RNDHIAXO	3		
351167	RNDLIAXO	1		
351167	ROLDIAXP	2		
351167	ROLFIAXO	2		
351167	RPPYIAXO	2		
351167	RVTNIAXP	2		
351167	RYANIAXO	2		
351167	SDNYIAXP	3		
351167	SGRNIAXP	1		
351167	SLTRIAXO	2		
351167	STANIAXO	1		
351167	STCYIAXP	1		
351167	STPNIAXP	1		
351167	STVLIAXO	2		
351167	<b>SWCYIAXO</b>	1		
351167	TABRIAXO	3		
351167	<b>TFFNIAXO</b>	1		
351167	THRMIAXP	1		
351167	TOLDIAXO	1		
351167	TRARIAXO	1		

Page 16

SAC	Wire Center	Complaints/1K		
351167	TRMLIAXO	1		
351167	<b>VOLGIAXO</b>	2		
351167	WADNIAXP	3		
351167	WASHIAXO	1		
351167	WCHSIAXO	2		
351167	<b>WDBIIAXO</b>	2		
351167	WHCHIAXO	2		
351167	WLBGIAXO	1		
351167	WLKRIAXO	2		
351167	WOTNIAXP	1		
351170	<b>ADARIAXO</b>	1		
351170	<b>ADBNIAXO</b>	2		
351170	ALBIIAXO	2		
351170	<b>APTNIAXO</b>	1		
351170	ATLSIAXO	2		
351170	AVOCIAXO	2		
351170	BLLVIAXO	0		
351170	<b>BNNTIAXO</b>	4		
351170	BOTNIAXO	2		
351170	BRWRIAXO	1		
351170	BYRDIAXO	2		
351170	CHRLIAXO	2		
351170	DLMRIAXO	2		
351170	DRNTIAXO	1		
351170	DWTTIAXO	0		
351170	<b>EDVLIAXP</b>	2		
351170	EXIRIAXO	2		
351170	FNTLIAXO	1		
351170	FRBGIAXO	1		
351170	FRFDIAXC	2		
351170	FRMTIAXO	2		
351170	<b>GNCTIAXO</b>	1		
351170	<b>GNFDIAXO</b>	2		
351170	GRNEIAXO	2		
351170	GTCTIAXO	1		
351170	HLBRIAXO	2		

Page 17

SAC	Wire Center	Complaints/1K		
351170	HRLNIAXT	2		
351170	JNVLIAXO	2		
351170	LCLRIAXO	2		
351170	LSBNIAXO	2		
351170	LWDNIAXO	5		
351170	LWMRIAXO	2		
351170	MDRDIAXO	2		
351170	MINDIAXO	3		
351170	MINGIAXO	1		
351170	MLRSIAXO	3		
351170	MNNGIAXO	2		
351170	MRRKIAXO	2		
351170	<b>MSCWIAXO</b>	1		
351170	NHTNIAXC	1		
351170	NWSHIAXO	2		
351170	NWTNIAXC	1		
351170	ROCHIAXO	2		
351170	SABLIAXP	2		
351170	SHLBIAXO	4		
351170	<b>SMNRIAXO</b>	1		
351170	STWDIAXO	3		
351170	TPTNIAXO	1		
351170	WSBGIAXO	1		
351178	AFTNIAXO	1		
351178	AGNCIAXO	2		
351178	ALCYIAXO	2		
351178	ALDNIAXO	1		
351178	ALPHIAXO	1		
351178	ANWOIAXO	2		
351178	ARGYIAXO	2		
351178	ARISIAXP	2		
351178	ATTCIAXO	2		
351178	AUBNIAXO	3		
351178	<b>BCKYIAXO</b>	1		
351178	<b>BGLYIAXO</b>	2		
351178	BITNIAXO	2		

Page 18

SAC	Wire Center	Complaints/1K		
351178	BKBGIAXO	2		
351178	BLBGIAXO	5		
351178	<b>BNTNIAXP</b>	4		
351178	BRNDIAXO	2		
351178	<b>BSSYIAXO</b>	2		
351178	CFVLIAXO	1		
351178	CHLCIAXO	3		
351178	CHRTIAXC	2		
351178	CLFDIAXO	2		
351178	CLITIAXO	2		
351178	CNCNIAXO	3		
351178	CNRPIAXO	1		
351178	CNSVIAXO	2		
351178	CNVLIAXO	2		
351178	DDHMIAXO	1		
351178	DGNLIAXO	3		
351178	DNMKIAXO	2		
351178	DNSNIAXO	2		
351178	DODSIAXO	1		
351178	<b>DOWSIAXO</b>	1		
351178	<b>ELDNIAXO</b>	2		
351178	<b>FASNIAXO</b>	4		
351178	<b>FONDIAXO</b>	2		
351178	FRTNIAXO	2		
351178	<b>FYTTIAXO</b>	1		
351178	<b>GDVWIAXO</b>	1		
351178	GRVTIAXO	2		
351178	HDRCIAXO	1		
351178	<b>HGTNIAXO</b>	2		
351178	HLBOIAXO	2		
351178	HSTNIAXO	1		
351178	JAMCIAXO	2		
351178	KLTNIAXO	3		
351178	KNVLIAXC	1		
351178	LACNIAXO	2		
351178	LBCTIAXO	2		

SAC	Wire Center	Complaints/1K		
351178	LBVLIAXO	2		
351178	LCRGIAXO	0		
351178	<b>LGTNIAXO</b>	1,		
351178	LKVWIAXO	1		
351178	<b>LMSPIAXO</b>	1		
351178	<b>LNBOIAXO</b>	4		
351178	<b>LNGVIAXO</b>	2		
351178	LNTRIAXO	1		
351178	LOVLIAXO	2		
351178	LTTSIAXO	2		
351178	LUCSIAXP	2		
351178	LWLRIAXO	1		
351178	LYTNIAXO	2		
351178	MILOIAXO	2		
351178	MKBGIAXO	2		
351178	MLCHIAXO	2		
351178	MLTNIAXO	1		
351178	MNPLIAXC	1		
351178	MONRIAXO	2		
351178	MORVIAXO	2		
351178	MRBGIAXO	3		
351178	MRDLIAXO	2		
351178	MRTHIAXO	2		
351178	MTAYIAXC	2		
351178	<b>MTRSIAXO</b>	2		
351178	<b>MTUNIAXO</b>	3		
351178	<b>MYNRIAXO</b>	1		
351178	MYSTIAXO	2		
351178	NCHLIAXO	3		
351178	<b>NWLLIAXO</b>	2		
351178	NWLNIAXO	2		
351178	<b>NWVRIAXO</b>	2		
351178	OKVLIAXO	2		
351178	OLDSIAXO	1		
351178	OLLIIAXO	2		
351178	OTLYIAXO	3		

SAC	Wire Center	Complaints/1K		
351178	PCWDIAXO	2		
351178	PELLIAXO	2		
351178	<b>PEORIAXO</b>	1		
351178	PERUIAXO	2		
351178	PLANIAXO	2		
351178	PLLNIAXO	2		
351178	<b>PMCYIAXO</b>	3		
351178	PRMRIAXO	2		
351178	<b>PSVLIAXO</b>	2		
351178	PTSNIAXO	2		
351178	<b>RCKTIAXO</b>	2		
351178	<b>RCLDIAXO</b>	2		
351178	<b>RDNGIAXO</b>	3		
351178	<b>RMBRIAXO</b>	2		
351178	RNDAIAXO	2		
351178	RSSLIAXO	2		
351178	RVSDIAXO	2		
351178	RWLYIAXO	2		
351178	SALMIAXO	2		
351178	SCHSIAXO	1		
351178	SHCYIAXO	3		
351178	SOLNIAXO	4		
351178	STLCIAXO	1		
351178	SYMRIAXO	2		
351178	TNGLIAXO	3		
351178	TRACIAXO	2		
351178	UNVLIAXO	3		
351178	UTE IAXO	2		
351178	VAILIAXO	2		
351178	WACMIAXO	1		
351178	WMSNIAXO	1		
351178	WNFDIAXO	2		
351178	WPLLIAXO	1		
351178	WSPNIAXP	1		
351248	DPRVIAXO	0		
351248	MTZMIAXO	3		

Page 21

## **Report 5 - Service Quality and Emergency Certification**

§ 54.313(a)(5) Certification that it is complying with applicable service quality standards and consumer protection rules

§ 54.313(a)(6) Certification that the carrier is able to function in emergency situations as set forth in §54.202(a)(2)

### Response:

See report certification - Certifications include compliance with service quality standards, consumer protection, and the ability to function in emergency situations.

# **Report 6 - Company Price Offering Report**

§ 54.313(a)(7) The company's price offerings in a format as specified by the Wireline Competition Bureau

Response: The Wireline Competition Bureau has not specified the format this data is to be provided in nor has this been approved by the Office of Management and Budget (OMB). This data will be provided once the OMB acceptance has been published in the Federal Register and the WCB has specified the format per FCC 11-161 ¶54.313(a)(7).

### **Report 7 - Holding and Operating Company Report**

§ 54.313(a)(8) The recipient's holding company, operating companies, affiliates, and any branding (a "dba," or "doing-business-as company" or brand designation), as well as universal service identifiers for each such entity by Study Area Codes, as that term is used by the Administrator. For purposes of this paragraph, "affiliates" has the meaning set forth in section 3(2) of the Communications Act of 1934, as amended

Response: The Office of Management and Budget (OMB) has not approved this new requirement. This data will be provided once the OMB acceptance has been published in the Federal Register per FCC DA 12-147 II.A.12.

# **Report 10 - Residential Local Service Rates Report**

§ 54.313(h) Additional voice rate data. All incumbent local exchange carrier recipients of high-cost support must report only their flat rates for residential local service, as well as state fees that are below the local urban rate floor as defined in § 54.318 of this subpart, and the number of lines for each rate specified. Carriers shall report lines and rates in effect as of June 1.

No rates are below the \$10 floor in lowa.

* ***			Res. Local Mandatory				
			Service	S	tate USF	EAS	
SAC	SPIN	Exchange	Charge	State SLC	Fee	Charge	Loops

### **Annual Report Certification**

June 26, 2012

 $\Lambda I I X I$ 

In accordance with FCC 11-161 ¶581, this form is to certify that all the information contained in this report is accurate to the best of my knowledge. I acknowledge my certification is subject to the penalties for false statements imposed under 18 U.S.C. §1001.

I, John Fletcher, am General Counsel for Windstream Communications and certify that I am authorized to execute this certification on behalf of Windstream and the facts set forth in this report are accurate to the best of my knowledge, information and belief.

Pursuant to the requirements under 47 C.F.R. §54.313(a)(5) and §54.313(a)(6) Windstream also certifies to the respective State Regulatory Commission that:

- 1) Windstream has established operating procedures designed to facilitate compliance with applicable consumer protection rules.
- 2) Windstream has established operating procedures designed to facilitate compliance with applicable service quality standards. Where applicable Windstream reports service quality standards to State Commissions.
- 3) Windstream has established operating procedures that allow it to function in emergency situations as set forth in 47 C.F.R §54.202(a)(2). Specifically, Windstream has a reasonable amount of back-up power to ensure functionality without an external power source, is able to reroute traffic around damaged facilities, and is capable of managing traffic spikes resulting from emergency situations.
- 4) Windstream certifies that all federal high-cost and CAF support was used in the proceeding calendar year and will be used in the new calendar year only for the provision, maintenance, and upgrading of facilities and services for which the support is intended.

Dated this 21 day of June 2012
John Fletcher
General Counsel
Windstream Communications
4001 Rodney Parham Rd.
Little Rock, AR 72212
SUBSCRIBED AND SWORN to before me this 21 day of June 2022 NOTA PUBLIC #12349466 EXPIRES  My Commission Expires: